M. A. R. 57 (Rule 116)
Measurement Book

No. E 491006

rial No. .....
me of work ..... From ..... To .....
me of Contractor of nature of Agency.....
te of commencement of work.....

ate	Full description, etc, of work	Number	Dimensions		Depth	Contents	Reference to last Measurement
	2	3	Length 4	Breadth 5	6	7	8
	Name of work :- Restoration and Improvements of Roads and Drains in AYR Layout, Shettyhalli Village, R.R. Layout of Chikkasandra village and Abigere village roads, BTS village, Vishveshwaraiah village, Royal Enclave and Sidedahalli old village roads Dugged by BWSSB to lay water supply and UGD lines under 110 villages in ward No 12 & 14 shettyhalli						
	Job code :- 012-22-000001						
	A.S — EE/DD/AS/05/2022-23. Date-17-05-2022						
	T.S — CE/D2/TS/28/2021-22 dt 05-10-2021.						
	Work order :- EE/DD/WO/14/2022-23. dt/27-05-2022						

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions (Present measurements)				Contents (upto)	Date / Reference to Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
		unit	Qty	Rate	Amount	Qty	Amount
①	Removing & Refixing stone slabs	sqm	2787.30	112.41	313320.39	2787.30	313320.39
②	Earthwork Excavation in ordenary soil.	cum	7526.423	227.75	1714368.80	7526.423	1714368.80
③	scarifying by mechanical stone metal crust 50 to 100mm thick.	sqm	18849.51	41.75	786967.04	18849.51	786967.04
10	Leading charges for scarified qty	cum	1507.96	31.03	46792.02	1507.96	46792.02

Received

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,

M. A. R. 57 (Rule 116)
Measurement Book

No. E 491007

rial No. .....
me of work ..... From ..... To .....
me of Contractor of nature of Agency.....
te of commencement of work.....

ate	Full description, etc, of work	Present measurements Dimensions				Contents	up to date Reference to last Measurement
	2	Number	Length	Breadth	Depth		
		Unit 3	Qty 4	Rate 5	Amount 6	Qty 7	Amount 8
12	P/F stone dust in. foundation to required depth	cum	880.90	1330.60	1172125.54 1172120.22	880.90	1172125.54 1172120.22
15	Construction of granular Sub - base	cum	2597.59	2014.67	5233806=00 5233804.59	2597.59	5233806=00 5233804.59
16	P/L wet mix macadam Screening	cum Execution	4387.01	2021.29	8867415.40 8867419.44	2597.59 4387.01	8867419.44 8867415.40

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಿಡ್ಲಘಟ್ಟ ಉಪವಿಭಾಗ

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions (Present measurement)				Contents upto Date		Reference to last Measurement	
		Number	Length	Breadth	Depth				
1	2	3	4	5	6	7		8	
		Unit	Qty	Rate	Amount	Qty		Amount	
17	Clearing the existing black topped surface	Sqm	2991.00	5.35	16001.85	2991.00		16001.85	
18	P/A Prime coat with SS bitumen emulsion	Sqm	18858.51	34.26	646092.55	18858.51		646092.55	
19	P/L Dense graded bituminous ~~Macadam~~	Cum	942.93	7365.73	6945334.64	942.93		6945334.64	
	Tack coat	Sqm	18858.51	12.85	242331.85	18858.51		242331.85	

M. A. R. 57 (Rule 116) **No. E 491008**

Measurement Book

rial No. .....

me of work ..... From ..... To .....

me of Contractor of nature of Agency.....

e of commencement of work.....

ite	Full description, etc, of work	Present measurements Dimensions				Contents up to Date	Reference to last Measurement
	2	Number	Length	Breadth	Depth		
		Unit 3	Qty 4	Rate 5	Amount 6	Qty 7	Amount 8
21	P/L Bituminous -concrete 40mm thick.	cum.	628.79	8534.82	5366609.46 5366607.76	628.79	5366609.46 5366607.76
22	Road Marking with thermoplastic compound	Sqm	655.06	459.29	300862.51	655.06	300862.51
23	S/I Moulded shank Raised nos. Pavement markers.	NO	200.00	360.79	72158.00	200.00	72158.00

Sub Total → 31724222.41

12=1.95T → 3806906.68

Total → 35531129.09

Checked

Checked

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Refers to la Measur
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	3553129=00 33019409=00 Three Crore thirty lakh Nineteen thousand Four Hundred Nine ny 251720=00		Total Amount	=		3,17,24,175. 3172422	
			GST 12%	=		38,06,90. 380690	
			Grand total	=		3,55,31,075. 3553129=0	

Certificate :-

(1) The above work has been completed satisfactorily.

(2) The debris has been removed and disposed from the work spot.

There is NO Departmental Issues to the contractor.

Agreed
31/7/22

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಿಜಿಎಂಪಿ, ಬೆಂಗಳೂರು

Audited and admitted for Rs.

Passed by Cheque for Rs.

(Three Crore thirty lakh Nineteen thousand Four Hundred Nine ny)

by adjust...

Accounts Superintendent Exe. Engineer

B.B.M.P. Tyagarajanagar Division

M. A. R. 57 (Rule 116)
Measurement Book

No. E 491009

ial No. .....
me of work..... From ..... To .....
ne of Contractor of nature of Agency.....
e of commencement of work.....

te	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
	2	3	4	5	6	7	8



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬೆಂಗಳೂರು